


Instruction



System Found The USB Device
Click **"Next"** To Continue



Insert The Driver Disk
Find out the **"Win98-2000"**
Click **"Next"** To Continue




System found the driver from your disk
Click **"Next"** To Continue




System will run **"InstallShield Wizard"**
Click **"Next"** To Continue



Select Folder Where Setup will install file
Click **"Next"** To Continue



After Installing, you will find out
a **"Quick Path"** On The DeskTop



After Running **"PC-Linq"**
It Will run New Work Window
Please note the signal at Right bottom
It will display **"Green Light & Red Light"**

* **Please install this driver to
another PC. (Same Step)**

After Installing the driver, please run
the software"PC-Linq" on the desktop.
The two PCs will run the same window.

* Note: The Right Bottom should have 2 Green lights.

